

## ZERO AIR FILTER



Calibration of the NOA for gas measurement also requires a gas contains low levels (< 1 ppb) of NO. This is easily produced from room air using a cartridge containing KMnO<sub>4</sub> and activated carbon. The trap has sufficient capacity for several years of use.  
Part Number: CACT 01400