

## ZERO AIR FILTER



Calibration of the NOA for gas measurement also requires a gas contains low levels ( $< 1$  ppb) of NO. This is easily produced from room air using a cartridge containing  $\text{KMnO}_4$  and activated carbon. The trap has sufficient capacity for several years of use.

Part Number: CACT 01400